

## AC/DC電流表

- Dual Slope A/D Converter Accuracy Less Than 0.2% of F.S.
- Large Size LED Display,25.4mm Easy To Monitor.
- Input 4~20mA,To Measure Moisture, Temperature or pressure.
- Easy To Measure High Current With CT.

 AA-24T  
電流表

 AA-24T -1  
電流表



 DA-24T  
電流表

 DA-24T-1  
電流表

 DA-24T-2  
電流表

**Specification**

Type	AC Current Meter		DC Current Meter		
Model	AA-24T	AA-24T-1	DA-24T	DA-24T-1	DA-24T-2
Measuring Range	0~5A	0~200mA	0~5A	0~200mA	4~20mA
Input Voltage	AC Voltage				
Power Supply	AC 110V/220V 50/60Hz 5VA max.				
Display Range	1999				
Display Method	25.4 mm 7-Segment Red LED				
Converting Method	Dual Slope A/D Converter				
Accuracy	$\pm 0.2\%$ of F.S.				
Response Time	2 Sec				
Dielectric Strength	2.5KV/1 min.				
Insulation Strength	100MΩ/500VDC				
Circumstance	-20°C ~+60°C, 35%~85%RH				
Weight	310g				

**Dimension**

**Connection Diagram**


## Illustration

**SW - 1**


Input Range Max.	NO. of SW-1					Input Impedance
	1	2	3	4	5	
1.999mA	ON	×	×	×	ON	100 Ω
19.99mA	×	ON	×	×	ON	10 Ω
199.9mA	×	×	ON	×	ON	1 Ω
5.0 A	×	×	×	△	△	0.1 Ω
Remarks	“△” Is Optioned, ON or OFF Is Dependent On The Amplification					

**SW - 2**


Decimal Point	NO. of SW-2			Decimal Point Selecting Is Independent ON The Amplification.
	1	2	3	
1	×	×	ON	
2	×	ON	×	
3	ON	×	×	

## How To Measure DC Current


Current &lt; 200mA




Current &gt; 200mA



Current &lt; 200mA



Current &gt; 200mA




## How To Apply Current Meter To Digital Scale Meter

 Amplification &  
Decimal Point  
Selecting


 SW-I & SW-II  
Selecting

 Zero Point or  
Offset  
Adjusting

Display


 Span  
Adjusting

Display



Ex. Input 4~20mA , Full Scale 100.0

$$Dz = -4 \times 1000 / (20 - 4) = -250 \quad <\text{After Opening The Input Circuit, To Adjust The Zero Trimmer}>$$

$$D = 100.0 \quad <\text{When The Input Current} = 20 \text{ mA, To Adjust The Span Trimmer}>$$